



impiego

macchina rettilinea su finezza 3 a 1 filo.
Si consiglia di lavorare a 3 o più guidafilili.

colori

chinè
Non sono riproducibili colori a campione.

solidità

secondo le norme UNI/ISO; per i rigati
con colori contrastanti, è necessario
richiedere solidità specifiche ed eseguire
test di lavaggio.

finissaggio industriale

vaporizzare abbondantemente in fase di
stiro. Per ottenere una mano più gonfia e
quindi una maglia più curata, è consigliabile
un lavaggio con un minimo di ammorbiden-
te specifico.

tutti i colori sono pronti per campionatura

per informazioni sull'utilizzo dell'artico-
lo e dei bagni ottimali di tintura, vi pre-
ghiamo di richiedere la scheda tecnica.

use

flat-knitting machine gauge 3 for 1-ply
It is suggested to knit 3 or more
threadguides.

colours

chine
We cannot match colours in this quality.

fastness

in compliance with UNI/ISO norms;
for striped garments with contrasting
colours, it is recommended to ask for
specific fastness and carry out washing tests.

industrial finishing

steam generously during ironing.
Wash with a minimum dose of appropriate
softner for a more voluminous touch and a
cleaner feel.

all colours are ready for sampling

for any information regarding the use
and dye-lot sizes of the yarn please ask
for the technical sheet.

